


Clutch Pedal Depressed w/ Pivot Stud Length Too Long



Interference w/ corner of PP housing HERE
Prevents clutch disc from completely disengaging

Clutch Pedal Released w/ Pivot Stud Length Too Short

